

**CENTRAL MAINE POWER COMPANY  
RESPONSE TO EXAMINER'S DATA REQUEST NO. 5  
DOCKET No. 2008-255**

**October 21, 2008**

**EX-05-18**

- Q.** (Volume X, Page 45 of 169) Was the use of voltage sensing switches investigated to reconnect the unfaulted section of line for the situation where a transformer is tapped off of the line? If not, why not? As part of your response, please detail what the impact on study results would be if they were considered.
- A.** Due to the nature of the violations to be mitigated, Automatic Sectionalizing was not considered.

**Response Prepared By:**

Paul Lerley  
System Planning Engineer

**Response Submitted By:**

David Conroy  
Manager of System Planning