

**CENTRAL MAINE POWER COMPANY
RESPONSE TO EXAMINER'S DATA REQUEST NO. 5
DOCKET No. 2008-255**

CONFIDENTIAL

October 20, 2008

EX-05-19

Q. (Volume X, Page 75 of 169) Please identify Section 87 and explain why it was outaged with Sections 61 and 61A.

A. Section 87 is a 115 kV line between the Norway and Kimball Road substations. There is no breaker at the Norway end of Section 61. A fault on Section 61 must be cleared by tripping breaker K87-1. This protective action opens Section 87 in addition to Sections 61 and 61A.

This response is confidential and is being provided under the terms and conditions of First Revised Protective Order No. 2, Critical Energy Infrastructure Information, dated August 27, 2008.

Response Prepared By:
Paul Lerley
System Planning Engineer

Response Submitted By:
David Conroy
Manager of System Planning